Attachment 2

The finding that the refrigeration was insufficient misdiagnoses or misidentifies the cause of the deficiency. Whereas, the inspector suspected the motor or the internal refrigerating mechanism as the source, the fact that the containers holding food had between and among the ample space for the chilled air to escape was the cause of the discrepan

The imperatives and responsibilities of preperatio I sholdered alone that day; this unforsee circumstance delayed the full and proper packing of the area at issue. Normally, this area is packed earlier, and the chilled air is thereby properly trapped, thus insuring proper cold temperature. From the following morning forward, I prepare this are first and completely. I fully acknowledge my oversight, my responsibility for this matter, and I have resolved the problem to satisfaction

Attachment 2

Ken Sanderson

602 327 0196160

CUSTOMER'S ORDER NO.	DEPARTMENT	DATE 7/24/15

NAME Mama Teresa Pizzeria

ADDRESS

CITY, STATE, ZIP

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RETD.	PAID OUT

	QUANTITY	DESCRIPTION	PRICE	AMOUNT
1		Randell Cooler		
2		Holein Evaporator		
3		Soldered - Tested - Okay		
4		Evacuated 500 microns		
5		Charged R134A.		
6				
7		2# R134A		20 -
8		Repaired Fan & Tool - To get		
9		air control		
10		Ken - 2hr		130 -
11				
12				$150 0
13				
14		Paid $100		
15		7/24/15 KK		
16				
17				
18				

RECEIVED BY

A-5805
T-46320/46350

KEEP THIS SLIP FOR REFERENCE

01